

**MONUMENT RECORD**  
**State of Indiana - County of Monroe**

**Section: 22**


**Township: 10 North**

**Range: 1 West**

**Corner ID: Wash O-17**

**Monument Description & Remarks: Brass Spike set. Survey Sign not set**

**References On File: Mike Mundy survey, Frank Thomas & Clara Mae Farnsley (1991); Douglas R. Curry survey, Jack Armes (1993); & Bledsoe Tapp & Riggert, Inc. survey, Exhibit "A" (1997); on file in Surveyor Office**



I, Kevin P. Enright, Monroe County Surveyor, hereby certify that document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code and the above data is given under my hand and seal this 29th day of April, 2008.

Administered by the Monroe County Surveyor Review Board

Date: 5-13-2008

